

Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
	View of the roofing membrane at townhouse building #2; note the standing water.
	View of the rooftop at townhouse, building #3, in the background.
	Close-up view of the rooftop at townhouse, building #3.

\bigtriangleup	
AIRO	

Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
08/26/2008	View of the rooftop at townhouse, building #4; the red water slick has algae growth.
08/26/2008	View of the roofing membrane at townhouse building #5, with townhouse building #4 in the background; note the standing water on both roofs.
08/26/2008	View of the rooftop at townhouse, building #5, looking south.



AIKU	
Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
08/26/2008	View of the typical roof drain on the townhouse buildings.
	View of the typical air conditioning
	condenser on the townhouse buildings.
	View of the typical chimney flue on the townhouse buildings.



AIRO	
Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
	View of the porte cochere roof from the tower building; the gravel ballast appears to be placed on a Firestone TPO roofing membrane.
	View of the Firestone thermoplastic polyolefin (TPO) single ply roof membrane installation at the elevator penthouse, typical at all buildings of the Subject Property, looking southwest. The fan hood, right side photo, is the original elevator room exhaust fan and is now inactive and has been replaced with an air-conditioning unit.
	Another general view of the Firestone single-ply TPO roof membrane installation at the elevator penthouse, looking northwest; the roof access hatch is open at the rear far left of the photo. The square fan hood behind the inoperable exhaust fan is the exhaust fan that ventilates the firemen's staircase. The newer units, rear of photo at right, are the electrical closet exhaust fan, and at left, the trash chute exhaust fan.



Roof & Elevator Equip-Description




Harrison West Condominiums-CA-Photos

Another general view of the Firestone single-ply TPO roof membrane installation at the elevator penthouse, looking northeast. The fan-hood in the foreground is an inactive elevator penthouse exhaust fan; the room is now air-conditioned. The square fan-hood ventilates the fireman's staircase; at the rear and left side of the photo, is the trash chute exhaust fan and right of it is the electrical closet exhaust fan.



View of the roof drain in the northwest corner of the elevator penthouse roof; note the strainer cap is tilted and should be corrected. Also note the parapet scupper to the right of the drain and the several patches on the single ply roofing membrane.



View of the Firestone single-ply TPO roof membrane installation at the primary tower roof, looking east; note the patches in the membrane.



Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
	View of the Firestone single-ply TPO roof membrane installation at the primary tower roof, looking north along the west side; note the dirt accumulation on the membrane, indicating a low spot on the roof.
07/16/2008	Close-up view of the precast concrete support pad, at the rooftop railing; note the black roofing membrane wear surface applied to the Firestone membrane under the pad.
	View of the Firestone single-ply TPO roof membrane installation at the primary tower roof, looking north along the east side; note the dirt accumulations on the membrane, indicating low spots on the roof.

Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
07/16/2008	View of the numerous patches in the Firestone single-ply roof membrane at the primary tower roof.
OTACHS/ 2008	Close-up view of a dirt accumulation at the east side of the primary tower roof, looking south; low spots in the roof construction together with higher locations of the two roof drains create this condition. Scuppers through the parapet wall would eject runoff off the building in the event of a roof drain blockage. Membranes should be cleaned periodically to prevent organic build-up from occurring.
07/16/2008	Close-up view of typical roof drain; the drain was covered by a perforated flat metal diamond plate that has replaced the strainer cap.


Architectural Investigative Reports & Opinions 525 Taggert Road #63 - Salem OR 97304 Office/Fax: 503.585.0872 sam@airo-llc.com



Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
07/16/2008	View of the typical roof scupper overflow installation; overflow drains redirect runoff through parapet walls to daylight.
07/16/2008	View of more patches in the Firestone primary tower roof membrane at the west side, looking south.
	Close-up view of the railing attachment to bearing walls at the tower roof; clips appear to be set in mastic and bolted to the concrete bearing walls. The sheet metal reglet below the bottom railing attachment clip receives the rooftop membrane that extends up and underneath it.



AIRO	Deef & Floueter Fruin Description
Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description View of the firemen's staircase access to the elevator penthouse and rooftops.
	View of the electrical controls for the exhaust fans that are located in the mechanical chase adjacent to the firemen's staircase at the rooftop.
07/16/2008	View of the fuse-box power-disconnect switches for the exhaust fans that are located in the mechanical chase.





Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
Image: Solid West Condominants CA Thoose Image: Solid West Condominants Image	View of cable traction elevator machine room at lifts #1 & #2.
	Close-up view of elevator control units for lifts #2 & #3 in the elevator penthouse. Control operators are by Schindler. The maintenance vendor is Thyssen-Krupp.
<section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header>	View of the 2008 Minimum Maintenance & Test Standards maintenance log for elevator #1; the most recent inspections occurred on May 25th.





AIKO	
Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
<image/> <image/> <image/> <image/> <image/> <image/>	View of the 2008 Minimum Maintenance & Test Standards maintenance log for elevator #2; the most recent inspections occurred on April 14th.
<image/>	View of the 2008 Minimum Maintenance & Test Standards maintenance log for elevator #3; the most recent inspections occurred on June 31st.
Normality Normality 1 1 1 <	View of the typical Westinghouse traction cable elevator machine; lift capacity is rated at 2500 lbs for all three passenger elevators.





Harrison West Condominiums-CA-Photos	Roof & Elevator Equip-Description
	View of the firemen's standpipe connection at the primary tower roof; this connection is located in the mechanical chase adjacent to the firemen's access staircase. Note the disconnect switches for the exhaust fans mounted on the main tower roof, at the left side of the photo.
07/16/2008	View of the elevator penthouse air- conditioning condenser mounted on the exterior sidewall of the penthouse.
	View of a typical exhaust fan located in one of four rooftop enclosure cabinets; exhaust fans expel air from the unit bathrooms and kitchens.





End of Photos

Note: Narrative text discussing items documented in these photos has been issued separately.

Architectural Investigative Reports & Opinions 525 Taggert Road #63 - Salem OR 97304 Office/Fax: 503.585.0872 sam@airo-llc.com